



Aeronautical Works, Kunovice, Czech Republic

Cero

Holding Company, Prague, Czech Republic

MANDATORY BULLETIN No. L23/028a

Sheet: 1
Of: 1
Enclosures: 4

Effectivity: Maintenance Manual for the L23 SUPER BLANÍK
(Do-L23-1031.3)

Reason: Adding of optional ILEK SC-7 vertical speed indicator and second RAZ indicator in the Maintenance Manual chapter 5 starting from ser. No. 968301.

Description: Maintenance Manual holders file the changed pages to the appropriate place in chapter 5 - List of eff. pages, page 1, Record of revisions, page 3, 5-10-00 pages 5,7 dated Sep 20/96.

To be accomplished not later than: Immediately after receiving this Bulletin.

To be accomplished by: Holder of Maintenance Manual

Cost covered by: No cost arise


Material availability: Receiving pages enclosed.

Validity: Since the date receiving

Manhours: 0



Manufacturer


46-04-23



Civil Aviation Inspection