## Company Limited Prague Czechslovakia

## MANDATORY BULLETIN No. L 13/058

Sheet: 1 **Of**: 1 Enclosure: 1/ 2sheets 2/ 3sheets Effectivity: 1. Instructions for the L13 pilot (issue No. 3) 2. L13A Sailplane Flight Manuals (Do-L13A-1011.1) Precisioning the strengt value of the weekest link of the Reason: wintchtow take-off cable. Description:The holders of the below presented documents should incorporate new sheets at the respective place: 1. Instructions for the L13 pilot (issue No.3) ....4; 22 and eliminate the respective original sheets of the same number. To be accomplished not later than: Immediately after the receipt of the Bulletin. To by accomplished by: Operator. Without any cost. Cost covered by: The replacement sheets from an enclosure of the Material availability: Bulletin. April 1, 1983 Validity: Manhours: Janeba Customer's Representative Manufacturer Olšan .... **OMNIPOL State Aviation Inspection Company Limited**