

member of

Unv Trust of Czechoslovak Aeronautical Works Prague Czechoslovakia

MANDATORY BULLETIN No. L 23/005a

Sheet	•	1	•	•	•		
of. Enclosu	r	ė	•	•	•	4	pages

Effectivity: The L 23 SUPER - BLANÍK Sailplane

Flight Manual (Doc. No Do-L23-1011.3).

Change of the text on titlepage concerning the SAI CSFR Reason:

approval of the Flight Manual by statement that SAI CSFR

approved sections 2, 3, 4 and 5 (in accordance with JAR-22 requirements). Further, a text describing the pilot's techniques for side-slip has been supplemented.

Description: The Flight Manual holders shall, replace old pages by

the new ones enclosed to this bulletin - title page,

0/1, 0/3, 4/9 dated November 30, 1990.

To be accomplished not later than: Immediately after receiving this Bulletin.

To be accomplished by: The Flight Manual holder.

Cost covered by: No costs arise.

Material availability: Revised pages are enclosed.

Since the date of receiving this Bulletin. Validity:

Manufacturer	Customer's Representative
ing. Zelinka	ing. Šácha

ing. Hýla	ing. Miškovský
State Aviation Inspection	Ministry of Foreign Trade