Cerro Company Limited Prague Czechslovakia

MANDATORY BULLETIN No. L 33/007a

Sheet: 1 2

Effectivity: L33 S/Ns 930203, 940210, 940304, 940309

Reason: Requirement of LBA-SRN.

Description: Installation of adapted emergency jettison.

To be accomplished not later than:

To by accomplished by: LET a.s. Kunovice

Cost covered by: LET a.s. Kunovice

Material availability: LET a.s. Kunovice

Validity: At the date of approval.

Manhours: 5 Man hours.

Ing. Fridrich

Manufacturer

Ing. Příhoda

State Aviation Inspection

Perform the installation according to drawing G010 600N.

B. MATERIAL REQUIRED FOR MODIFICATION OF ONE SAIL-PLANE

According to specification card G007 007N.

C. ILLUSTRATIONS

D. ADDITIONAL DOCUMENTATION

E. TOOLING REQUIRED

Tooling for work with rivets, upholstery and fittings.

F. SPARE PARTS IN SERVICE

Not affected.

G. WEIGHT

Not affected.

H. RECORD IN THE AIRFRAME LOGBOOK

L 33/007a

"Emergency cabin jettison installation accomplished according to drawing G010 600N."

Date:	Carried	out	pà:										
****					•0		• •	æ	*	• •	• •	• ;	

(legible signature)

I. ACCOMPANYING DOCUMENTATION

Sailplane Flight Manual & 33 SOLO - Not affected. Provisional Maintenance Manual L 33 SOLO - Description of jettison added.