

## member of

## QUIV Trust of Czechoslovak Aeronautical Works Prague

## MANDATORY BULLETIN No. L23/008a

Shee	t		•	1	
Of				1	

Effectivity: The L23 SUPER-BLAN(K Sailplane Enclosure: 10 pages

Flight Manual (Doc. No. Do-L23-1011.3).

Reason: Indusion of new requirements based on the operational experience

and the SAI CSFR restriction of the "half loop and half roll" and "half roll and half loop" in dual flight (according to

JAR - 22.3 paragraph).

Description: The Flight Manual holders shall replace old pages by the

new ones enclosed to this bulletin - 0/1, 0/3, 0/4, 1/3,

2/3, 2/4, 4/19, 4/20, 6/6, 8/3 dated May 30,1991.

To be accomplished not later than: Immediately after receiving this

Bulletin.

To be accomplished by: The flight Manual holder.

Cost covered by: No costs arise.

Material availability: Revised pages are enclosed.

Validity: Since the date of receiving this Bulletin.

ing. Šich ing. Šácha

Manufacturer Customer's Representative

ing. Příhoda ing. Miškovský

State Aviation Inspection Ministry of Foreign Trade