## OPERATING BULLETIN No. L 13/035

Sheet No.: 1 No. of Sheet: 1

Subject : Pilet's Metes for the L 13 Sailplane, 2nd and 3rd editions.

Reason : Scale of indicated air-speed in the performance characteristics(speed polar) chart has been misplaced by one place (10km/h).

Measures: Correct the values of indicated air-speed in Annex 2 - PERFORMANCE CHARACTERISTICS - by adding 10 (km/h), i.e. to read 60 instead of 50, 70 instead of 60, etc.

The chart im British system of units is to be corrected by increasing the original values by 5 (kts), i.e. to read 30 instead of 25,35 instead of 30, etc.

To be carried out: By the Operator immediately after the receipt of this bulletim.

Cost and Material: None.

The bulletin is valid when received by the Operator.

Čáslavský	ing. Lukas
Manufacturer's Representative	Customer's Representative
Kadleček	Pavlovský
State Aviation Inspection	Ministry of Foreign Trade