



OMNIPOL PRAHA ČESKOSLOVENSKO

MANDATORY BULLETIN No. L 13/046

Sheet No: 1
No. of Sheets: 1

Subject: The L 13 Blanik sailplanes of all Serial Numbers.

Reason: To supplement allowance for elevator deflection.

Measures: In the Technical Manual of the L 13 Sailplane (any edition), Part I - Technical Description, Chapter 1 - Sailplane Specification, para. 2 Permissible allowances - play (tolerance) - adjustment of control surfaces change the (upward) elevator deflection in the text and the associated figure to read $32^{\circ} + 2^{\circ}$ instead of 32° .

To be carried out: By the Operator immediately after the receipt of this Bulletin.

The Bulletin is valid when received by the Operator.

Čáslavský

Manufacturer's
Representative

Ing. Šácha

Customer's
Representative


30 November, 1977

Olšan

State Aviation
Inspection

Houdek

Ministry of
Foreign Trade



LET n. p., UH. HRADIŠTĚ - KUNOVICE