




OMNIPOL PRAHA ČESKOSLOVENSKO

MANDATORY BULLETIN No. L 13/053

Sheet No. : 1

No. of Sheets: 1



Subject: Extension of Mandatory Bulletin No. L 13/048.

Reason: Laps on spacers Dwg. No. L 13.201-22.01 have been reported even on sailplanes of lower Serial Numbers than those given in the Mandatory Bulletin No. L 13/048.



Measures: Delete the existing text of the first paragraph in Mandatory Bulletin No. L 13/048 and replace it with the following sentence: "The L 13 sailplanes of all Serial Numbers."



To be carried out: By the Operator immediately after the receipt of this Bulletin.



Costs and Material: None.

The Bulletin is valid when received by the Operator.



..... Ing. Janeba
Manufacturer's Representative

..... Ing. Šácha
Customer's Representative



May 29, 1981

..... Ing. Olšan
State Aviation Inspection

..... Zahrádka
Ministry of Foreign Trade

